



Work Order # 319666

Activity Code BMPINS
 Activity Description BMP INSPECTION
 Asset Storm Storage Basin
 Asset ID 21C115
 Asset Description TABB LAKES POND 2

Summary

Closed on 9/6/2017 by TRISTIAN BARNES.

Information

Work Order Information

Initiated 9/6/2017 11:08
 Schedule Start
 Schedule Finish
 Due
 Initiated By BARNEST
 Project
 Budget Number
 Source
 Maint Type
 Problem
 Priority
 Service Request
 Estimated Cost 0.00
 Authorization
 Assigned To
 Responsibility
 Reference #
 Group Project
 Incident
 Out of Service no
 Potential Service no
 Request

Started 9/6/2017 11:08
 Closed 9/6/2017 00:00
 Closed By BARNEST
 Hours 0.00
 Down Time 0.00
 Result
 Condition
 Actual Quantity 0.000
 Unit of Measure
 Asset Valuation Type
 Major Failure no
 Cancel Work Order no

Attachments

Attachments
(No Data)

Location

Address Information

Address type Address
 Street # 105
 Pre Dir
 Street Name BRIDGE WOOD
 Suffix DR
 Post Dir
 Subdesignation Z
 Cross Street
 Street 2 Name
 Street 2 Suffix
 Street 2 Post
 Direction
 Cross Street
 Street 3 Name
 Street 3 Suffix
 Street 3 Post
 Direction
 City, State, ZIP YORKTOWN
 State VA
 Zip Code 23693

Location Information

Location
 GPS X 0.0000
 GPS Y 0.0000

Comments

Comments

BMP outfall flows into other BMP. I have limited access to the entire BMP due to walking through various yards and fencing. I have checked various points previously. This meeting was to inspect on of the inlets and the drainage area. Mr. Layfrenaye met with Steve Shumaker and I. We noted that there was sediment in the drainage area, this is supported to be York County's easement. There did not appear to be enough to cause alarm, at this point. Tabb Lakes generally does a good job with maintenance and will contact me if there is an issue.