



Work Order # 319617

Activity Code BMPINS
Activity Description BMP INSPECTION
Asset Storm Storage Basin
Asset ID 21C114
Asset Description TABB LAKES POND 1

Summary

Closed on 11/29/2017 by TRISTIAN BARNES.

Information

Work Order Information

Initiated 11/29/2017 00:00
Schedule Start 11/29/2017 00:00
Schedule Finish 11/29/2017 00:00
Due
Initiated By BARNEST
Project
Budget Number
Source
Maint Type
Problem
Priority
Service Request
Estimated Cost 0.00
Authorization
Assigned To
Responsibility
Reference #
Group Project
Incident
Out of Service no
Potential Service no
Request

Started 11/29/2017 00:00
Closed 11/29/2017 00:00
Closed By BARNEST
Hours 0.00
Down Time 0.00
Result
Condition
Actual Quantity 0.000
Unit of Measure
Asset Valuation Type
Major Failure no
Cancel Work Order no

Attachments

Attachments
(No Data)

Location

Address Information

Address type Address
Street # 105
Pre Dir
Street Name BRIDGE WOOD
Suffix DR
Post Dir
Subdesignation Z
Cross Street
Street 2 Name
Street 2 Suffix
Street 2 Post
Direction
Cross Street
Street 3 Name
Street 3 Suffix
Street 3 Post
Direction
City, State, ZIP YORKTOWN
State VA
Zip Code 23693

Location Information

Location
GPS X 0.0000
GPS Y 0.0000

Comments

Comments

The area near the observation deck has filled in with more leaves. I've been in contact with Mr. Lafreny regarding this issue. The HOA knows they will have to dredge this area, specifically. The water is entering and exiting. There does appear to be one outfall pipe that has a buildup. This is within the county easement, however, it does not appear to be impairing the flow of water. A visual inspection of the "outfall" for the other pond appears to be okay, free flowing.